



909D/909D-A PGM Hat Tree Rack

Assembling Guide

- | | |
|-----------------|---------|
| (1) BASE | 1 pc. |
| (2) SPRING | 1 pc. |
| (3) INNER POLE | 1 pc. |
| (4) OUTER POLE | 1 pc. |
| (5) HAT HOLDER | 20 pcs. |
| (6) HOLDER BASE | 5 pcs |
| (7) TOPPER | 1 pc. |



(1)



(2)



(3)



(4)



(5)




(6)



(7)


PGMPlus



Step 2
Gently place **SPRING** on top
of the **BASE**.

Step 1
Place **BASE** firmly on the ground.

Step 3
Insert **INNER POLE** into the
BASE through **SPRING**.



*Make sure to twist the screw tightly after
INNER POLE is inserted into the **BASE**
completely.*

*Make sure to have **INNER POLE** standing on the end of the foot pedal.*



Step 4

Slide OUTER POLE over INNER POLE.



The top of INNER POLE must be aligned like this while stepping down the foot pedal.

When sliding OUTER POLE, make sure you are stepping down on the foot pedal with the top of INNER POLE aligned.

Step 5


Slide HOLDER BASE over OUTER POLE and twist the screw tightly. You may adjust the height based upon your need.





Step 6

Insert HAT HOLDER into SCREW RING respectively.



Congratulations !! Installation Complete